

Número de parte	P550949
Número de ítem	P550949
Aplicación Primaria	CUMMINS ISX
Descripción	LUBE FILTER, SPIN-ON FULL FLOW
Comentarios	Modified Efficiency Version of P559000
Reemplazo	
Partes relacionadas	P559000
Alternativas	

Información regional	
Estado	Active
Región	LATIN AMERICA (DLA)
Disponibilidad	DISPONIBLE
Empaque mínimo DLA	6
País de Origen	Mexico




Atributos		
Eficiencia 99%	30 Micron	30 Micron
Estándar de prueba de Ef.	ISO 16889	ISO 16889
D.I. Empaque	4.00 Inches	101.6 MM
D.E. Empaque	4.68 Inches	118.872 MM
Longitud	11.70 Inches	297.18 MM
Tipo de Media	Synthetic	Synthetic
Diámetro Externo	4.66 Inches	118.36 MM
Tamaño de Cuerda	M95 x 2.5	M95 x 2.5
Peso	3.5 Lbs	1.59 Kgs



# Cruces de Referencia

## P550949



Competidor	Número de parte competidor	Donaldson: P550949
BALDWIN	BD7153	OEM Eff Std Service
BALDWIN	BD7154 	OEM Eff Std Service
FLEETGUARD	40C0434	OEM Eff Std Service
FLEETGUARD	LF9000	OEM Eff Std Service
FLEETGUARD	LF9001	OEM Eff Std Service
FLEETGUARD	LF9011	OEM Eff Std Service
FLEETGUARD	LF9018	OEM Eff Std Service
FLEETGUARD	LF9070	OEM Eff Std Service
FLEETGUARD	LF9080 	OEM Eff Std Service
GONHER	GP9000	OEM Eff Std Service
GONHER	GP9001	OEM Eff Std Service
LUBER-FINER	LFP9000	OEM Eff Std Service
LUBER-FINER	LFP9001	OEM Eff Std Service
LUBER-FINER	LFP9007	OEM Eff Std Service
LUBER-FINER	LFP9008	OEM Eff Std Service
MANN & HUMMEL	WP12120 	OEM Eff Std Service
WIX	57745	OEM Eff Std Service
WIX	57746	OEM Eff Std Service
WIX	57746XD	OEM Eff Std Service
WIX	57748	OEM Eff Std Service

28/04/2015 Donaldson se reserva el derecho de modificar la información contenida en este documento sin previo aviso.