

| Número de parte | P558792 |
|---------------------|-------------------------------|
| Número de ítem | P558792 |
| Aplicación Primaria | CAT 4H-8792, 9H-4729, 6H-5932 |
| Descripción | FUEL FILTER, CARTRIDGE |
| Comentarios | |
| Reemplazo | |
| Partes relacionadas | |
| Alternativas | |

| Información regional | |
|----------------------|---------------------|
| Estado | Active |
| Región | LATIN AMERICA (DLA) |
| Disponibilidad | DISPONIBLE |
| Empaque mínimo DLA | 12 |
| País de Origen | Indonesia |

| Atributos | | |
|---------------------------|-------------|-----------|
| Eficiencia 99% | 10 Micron | 10 Micron |
| Estándar de prueba de Ef. | SAE J1985 | SAE J1985 |
| Diámetro Interno | 1.12 Inches | 28.448 MM |
| Longitud | 6.5 Inches | 165.1 MM |
| Tipo de Media | Cellulose | Cellulose |
| Diámetro Externo | 3.37 Inches | 85.598 MM |
| Peso | 0.44 Lbs | 0.2 Kgs |







Cruces de Referencia


P558792



Donaldson
SOLUCIONES DE FILTRACIÓN

| Competidor | Número de parte competidor | Donaldson: P558792 |
|-------------|--|--------------------------------|
| BALDWIN | PF223F | |
| BALDWIN | PF823 | REQUIRES (2) P558792 |
| BALDWIN | PF823E  | |
| BALDWIN | PF824 | |
| BALDWIN | PF829 | |
| CATERPILLAR | 1R0724 | |
| CATERPILLAR | 1S6811 | |
| CATERPILLAR | 1W2130 | |
| CATERPILLAR | 2H8792 | CAT Loader 966 with CAT engine |
| CATERPILLAR | 3I1379 | |
| CATERPILLAR | 4H8792 | |
| CATERPILLAR | 4H8860 | |
| CATERPILLAR | 4L4621 | |
| CATERPILLAR | 4L6777 | |
| CATERPILLAR | 4L6778 | |
| CATERPILLAR | 4M8641 | |
| CATERPILLAR | 4S5368 | |
| CATERPILLAR | 5L2772 | |
| CATERPILLAR | 5L7564 | |
| CATERPILLAR | 5M0473 | |
| CATERPILLAR | 5M0476 | |
| CATERPILLAR | 5M0953 | |
| CATERPILLAR | 5M473 | |
| CATERPILLAR | 5M476 | |
| CATERPILLAR | 5M953 | |
| CATERPILLAR | 5S5144 | |
| CATERPILLAR | 6H5931 | |
| CATERPILLAR | 6H5932 | REQUIRES (2) P558972 |
| CATERPILLAR | 7H0833 | |
| CATERPILLAR | 7H833 | |

| | | |
|---------------|---|--|
| CATERPILLAR | 8H0671 | |
| CATERPILLAR | 8H0835 | |
| CATERPILLAR | 8H4825 | |
| CATERPILLAR | 8H5148 | |
| CATERPILLAR | 8H835 | |
| CATERPILLAR | 8M5388 | |
| CATERPILLAR | 8M7S2S | |
| CATERPILLAR | 8M8641 | |
| CATERPILLAR | 8M9641 | |
| CATERPILLAR | 9H0537 | |
| CATERPILLAR | 9H1252 | |
| CATERPILLAR | 9H1252* | |
| CATERPILLAR | 9H4537 | |
| CATERPILLAR | 9H4565 | |
| CATERPILLAR | 9H4729 | |
| CATERPILLAR | 9H8792 | |
| CATERPILLAR | 9L25 | |
| CATERPILLAR | 9M9641 | |
| FLEETGUARD | FF116  | |
| GONHER | G1166 | |
| GONHER | G1166M | |
| LUBER-FINER | 364F  | |
| LUBER-FINER | L364F | |
| LUBER-FINER | L364F1 | |
| LUBER-FINER | LP364F | |
| MANN & HUMMEL | P934 | |
| MANN & HUMMEL | P934A | |
| SAKURA | F5501  | |
| TECFIL | P4H8792 | |
| TECFIL | PC116 | |
| TECFIL | PC4H8792 | |
| WIX | 2021P | |
| WIX | 33180 | |
| WIX | 33181 | |

| | | |
|-----|---|--|
| WIX | 33187 | |
| WIX | 33188 | |
| WIX | 33189 | |
| WIX | 33641 | |
| WIX | 33642 | |
| WIX | 59057 | |
| WIX | CW181MP | |
| WIX | CW189MP | |
| WIX | CW642MP  | |

28/04/2015 Donaldson se reserva el derecho de modificar la información contenida en este documento sin previo aviso.